


## Pareto: Failure by Training, Operator

Downtime of colorimeter for measuring copper concentration.


Last updated 2 February 2016 at 8:02 by Analyse-it Software, Ltd.



# Pareto: Failure

Downtime of colorimeter for measuring copper concentration.

Last updated 2 February 2016 at 8:04 by Analyse-it Software, Ltd.



# Pareto: Failure

Downtime of colorimeter for measuring copper concentration.

Last updated 2 February 2016 at 8:38 by Analyse-it Software, Ltd.

